Figure S1 (a-d) Downstream aerosols concentrations, cm^{-3}, for DMA Cases 1-4, with sheath and excess air flow 3 L min^{-1}, and aerosol and sample flow of 0.06-0.90 L min^{-1}. (e-h) Downstream concentrations for DMA Cases 1 and 5-7, with sheath air flow 3.0 L min^{-1}, sample flow 0.30 L min^{-1}, and excess air flow 2.94-3.06 L/min.